

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 18

Facility Name: Peach Bottom 3 Docket (050- 00278)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	Z - Other / Unknown	R - Refueling	050-00278/2009-005
160 - No communication / information not communicated	A - Administrative Support	A - Administrative	050-00278/2009-005
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2010-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
<hr/>			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00278/2009-005
146 - Evaluation LTA	E - Electrical	M - Maintenance / Repair	050-00278/2009-005
148 - Action not yet started or untimely	E - Electrical	M - Maintenance / Repair	050-00278/2009-005
Number of Items for this Docket: 3			
Percent of Total for this Docket: 17			
<hr/>			
Work Planning & Practices / IR			
182 - Work package quality LTA	E - Electrical	M - Maintenance / Repair	050-00278/2009-005
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00278/2009-005
185 - Procedural adherence LTA	Z - Other / Unknown	R - Refueling	050-00278/2009-005
185 - Procedural adherence LTA	Z - Other / Unknown	R - Refueling	050-00278/2009-005
185 - Procedural adherence LTA	Z - Other / Unknown	R - Refueling	050-00278/2009-005
185 - Procedural adherence LTA	Z - Other / Unknown	R - Refueling	050-00278/2009-005
185 - Procedural adherence LTA	Z - Other / Unknown	R - Refueling	050-00278/2009-005
185 - Procedural adherence LTA	Z - Other / Unknown	R - Refueling	050-00278/2009-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00278/2010-002
186 - Failure to take action / meet requirements	E - Electrical	G - Design	050-00278/2009-005
187 - Action implementation LTA	E - Electrical	G - Design	050-00278/2009-005
187 - Action implementation LTA	E - Electrical	G - Design	050-00278/2009-005
197 - Self-check LTA	Z - Other / Unknown	R - Refueling	050-00278/2009-005
Number of Items for this Docket: 12			
Percent of Total for this Docket: 67			
<hr/>			
Total Items for this Docket: 18			