

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 17

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 17

---

**Facility Name: Susquehanna 2 Docket (050- 00388)**

Details	Department	Work Type	Docket/Report
<b>Human-System Interface &amp; Environmnt / IR</b>			
170 - HSI or information availability / quality LTA	H - Health Physics	H - Health Physics	050-00388/2004-005
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 6</b>			
<b>Procedures &amp; Reference Document / IR</b>			
110 - No procedure / reference documents	P - Procedure Writers	G - Design	050-00388/2004-005
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00388/2005-003
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 12</b>			
<b>Problem Identification &amp; Resolution / IR</b>			
144 - Audit / self-assessment / effectiveness review LTA	H - Health Physics	H - Health Physics	050-00388/2004-005
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 6</b>			
<b>Work Planning &amp; Practices / IR</b>			
183 - Pre-job activities LTA	W - Work Control / Scheduling Outage Pla	M - Maintenance / Repair	050-00388/2005-003
188 - Work practice or craft skill LTA	G - Engineering	G - Design	050-00388/2005-003
188 - Work practice or craft skill LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00388/2004-005
188 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00388/2005-002
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00388/2005-003
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00388/2005-002
190 - Failure to stop work / non-conservative decision making	W - Work Control / Scheduling Outage Pla	H - Health Physics	050-00388/2005-003
198 - Worker distracted / interrupted	M - Mechanical	S - Surveillance	050-00388/2005-003
<b>Number of Items for this Docket: 8</b>			
<b>Percent of Total for this Docket: 47</b>			
<b>Procedures &amp; Reference Document / LER</b>			
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00388/2005-003-00
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 6</b>			
<b>Problem Identification &amp; Resolution / LER</b>			
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00388/2005-001-00
148 - Action not yet started or untimely	G - Engineering	F - Modification	050-00388/2005-003-00
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 12</b>			

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 17

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 17

---

**Facility Name: Susquehanna 2 Docket (050- 00388)**

Details	Department	Work Type	Docket/Report
<b>Training / LER</b>			
100 - Training LTA	O - Operations	O - Control Room Ops	050-00388/2005-003-00
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 6			
<b>Work Planning &amp; Practices / LER</b>			
190 - Failure to stop work / non-conservative decision making	G - Engineering	F - Modification	050-00388/2005-003-00
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 6			
<b>Total Items for this Docket: 17</b>			

---